Equine Veterinarians Australia

A Special Interest Group of the Australian Veterinary Association Ltd. ABN 63 008 522 852

VETERINARY REPORT ON BROODMARE FOR SALE

707

This examination is limited to an assessment of the reproductive matters below and should in no way be relied upon as a representation or expression of opinion as to breeding soundness. It is beyond the scope of this examination to definitively detect if this mare has been treated with Equity® Vaccine or any other medication.

Animal presented as:	*Fastnet Rose*	Age/DOB: 2013

(If unnamed) Sire:	Dam:

Breed: T Bred	Colour: Bay	Microchip No: 985100012029065

Owner (if known):	Address (if known):

Person requesting examination: Alison Hush	Place of examination: Davali Thoroughbreds, NSW

Draw brands and/or markings:
Mark whorls as X, scars as ➡

Rear aspect forelegs L R

Head & muzzle

187 3

Rear aspect hind legs L R

This mare was examined (please tick)		The mare was (please tick)		Reported last serve date
Under Sedation	✓	Pregnant		
Not Sedated		Not Pregnant	✓	
Other Physical Restraint				

(Please tick appropriate boxes - add additional sheets for details if required)

Ovaries	Y	N	Total Ovarian Dimensions (Measured by US)	Largest Follicle Diameter (Measured by US)	Comments
Manual Examination per Rectum	✓		Left: 6.1 cm x 6.2 cm + CL	Left: 3.1	CL present
U/S Examination	✓		Right: 3.5 cm x 5.0 cm	Right: 1.1	

Uterus	Y	N	Details		Vagina	Y	N	Details
Manual Examination per Rectum	✓				Manual Examination per Vagina	✓		
U/S Examination	✓				U/S Examination	✓		
Uterine Cysts		✓			Visual Examination per Speculum		✓	
Uterine Fluid		✓			Comments			
Comments			no endometrial folds consistent with anoestrous		Vulva	Y	N	Details
					Caslicked		✓	
Cervix	Y	N	Details normal		Comments		✓	
Manual Examination per Vagina	✓				Udder			
U/S Examination	✓				Visual Examination	normal		
Visual Examination per Speculum		✓			Manual Examination	normal		
Comments								

Other comments

Normal reproductive tract on palpation & scan

Date: 11/4/2018	Signed: M. Baltussen
Name (please print): Madalen Baltussen	Place stamp/write address here: 11788 Hunter Equine Vet 106 Macquarie St Merewether NSW2291
Contact Number: 0417 880 577	
AVA No: 9211	VPB No: N9591	